

MECHANICAL DISHWASHING REQUIREMENTS

Irreversible Registering Temperature Indicators

The 2013 Food Code States


4-703.11(B):

Temperature Measuring Devices, Manual and Mechanical Warewashing.

“High temperature dishwashers: an irreversible registering temperature indicator (examples shown below) is required to test the rinse water temperature. Rinse water temperature shall achieve a surface temperature of 160°F or more.”

If your establishment has a hot water mechanical ware washing operation you must purchase an irreversible registering temperature indicator

(If your Establishment does not have a HIGH Temperature ware wash machine this does not apply to you)

Plate Stimulating Dishwasher Thermometer	Dishwasher Temperature Labels Irreversible	Dishwasher Temperature Strips Irreversible
<p style="text-align: center;">DishTemp®</p> 	<p style="text-align: center;">Thermostrip DL</p> 	<p style="text-align: center;">Thermostrip DS</p> 
<p style="text-align: center;">www.thermoworks.com</p>	<p style="text-align: center;">www.thermometersite.com</p>	<p style="text-align: center;">www.thermometersite.com</p>

There are many options for irreversible temperature indicators, above are some for your guidance